

Notes

Reproduced from January 1964 MRN article Includes extra Signal Box windows Etching imagery above - blue for front half etch, red for rear half etch.

We cannot explain the shortened door bracing, but this seems to have been a fairly common feature of the ground frames construction.

Construction

Break up inner shell at rear half etched line
This will make it possible to fold up "corner posts"
The handrails are multilayered items,
Note the handrail fitting slot in the outer shell
Additional window cills are included - use the narrower strips

NOTE

Be careful not to distort the window parts, those illustrated have been stretched by overheating.

Produced by AMBIS Engineering 80 Westgate Street, Shouldham Kings Lynn, Norfolk, Pe33 0BH





